



Size Conversion Chart

64th's	Fraction	Inches	MM	64th's	Fraction	Inches	MM
1	1/64	0.0156	0.3969	34	17/32	0.5313	13.4938
2	1/32	0.0313	0.7938	35	35/64	0.5469	13.8906
3	3/64	0.0469	1.1906	36	9/16	0.5625	14.2875
4	1/16	0.0625	1.5875	37	37/64	0.5781	14.6844
5	5/64	0.0781	1.9844	38	19/32	0.5938	15.0813
6	3/32	0.0938	2.3813	39	39/64	0.6094	15.4781
7	7/64	0.1094	2.7781	40	5/8	0.6250	15.8750
8	1/8	0.1250	3.1750	41	41/64	0.6406	16.2719
9	9/64	0.1406	3.5719	42	21/32	0.6563	16.6688
10	5/32	0.1563	3.9688	43	43/64	0.6719	17.0656
11	11/64	0.1719	4.3656	44	11/16	0.6875	17.4625
12	3/16	0.1875	4.7625	45	45/64	0.7031	17.8594
13	13/64	0.2031	5.1594	46	23/32	0.7188	18.2563
14	7/32	0.2188	5.5563	47	47/64	0.7344	18.6531
15	15/64	0.2344	5.9531	48	3/4	0.7500	19.0500
16	1/4	0.2500	6.3500	49	49/64	0.7656	19.4469
17	17/64	0.2656	6.7469	50	25/32	0.7813	19.8438
18	9/32	0.2813	7.1438	51	51/64	0.7969	20.2406
19	19/64	0.2969	7.5406	52	13/16	0.8125	20.6375
20	5/16	0.3125	7.9375	53	53/64	0.8281	21.0344
21	21/64	0.3281	8.3344	54	27/32	0.8438	21.4313
22	11/32	0.3438	8.7313	55	55/64	0.8594	21.8281
23	23/64	0.3594	9.1281	56	7/8	0.8750	22.2250
24	3/8	0.3750	9.5250	57	57/64	0.8906	22.6219
25	25/64	0.3906	9.9219	58	29/32	0.9063	23.0188
26	13/32	0.4063	10.3188	59	59/64	0.9219	23.4156
27	27/64	0.4219	10.7156	60	15/16	0.9375	23.8125
28	7/16	0.4375	11.1125	61	61/64	0.9531	24.2094
29	29/64	0.4531	11.5094	62	31/32	0.9688	24.6063
30	15/32	0.4688	11.9063	63	63/64	0.9844	25.0031
31	31/64	0.4844	12.3031	64	1	1.0000	25.4000
32	1/2	0.5000	12.7000				
33	33/64	0.5156	13.0969				